

94300d

San Francisco District 1431 Harbor Bay Parkway Alameda, CA 94502-7070 Telephone: 510/337-6700

CERTIFIED MAIL RETURN RECEIPT REOUESTED

Our Reference: 2940291

September 15, 2003

Gerard Bautista, Superintendent of Operations Guam International Airport Authority P.O. Box 8870 Tamuning, Guam 96931

WARNING LETTER

Dear Mr. Bautista:

On August 1, 2003, FDA conducted an inspection of Guam International Airport Authority located at 355 Chalan Pasajero, Tamuning, Guam, which provides aircraft waste service at A.B. Won Pat International Airport. The observations made during the inspection revealed that the facility is in violation of Section 361 of the Public Health Service Act and the Interstate Conveyance Sanitation regulations at Title 21, Code of Federal Regulations, Part 1250 (21 CFR 1250). FDA's observations were listed on Form FDA 483, Inspectional Observations, which was issued to and discussed with Marc A. Gagarin, Chief Engineer. Form FDA 2528, Inspection Summary - Airline Service Area or Watering Point Sanitation, was also provided to Mr. Gagarin. Copies of both documents are enclosed for your ready reference.

During the inspection, the following observations were noted:

- 1. There is no backflow prevention device to the potable water line at the aircraft service area near the airstrip (21 CFR § 1250.67).
- 2. The vacuum breakers for the sanitizer solutions at the aircraft service area near the airstrip are not located at least 12 inches above the highest point of the water line (21 CFR § 1250.67).

The inspectional observations, identified above, are not intended to be an all-inclusive list of deficiencies. It is your responsibility to assure adherence with all applicable statutes and regulations enforced by FDA.

Based on the inspectional findings, we are classifying your facility as "Provisional" for interstate carrier use for a period of thirty (30) days. A "Provisional" classification means that the facility may continue to operate; however, significant correction of violations must be made by the expiration date. On or about that date, a re-inspection of this facility will be conducted to assure that corrections meet FDA requirements. If significant corrections are not made by the time of the next inspection, this facility will be reclassified as "Not Approved" for carrier use. Assignment of "Not Approved" status for food service facilities means that food and beverages from this facility may not be used by interstate conveyances until the violations have been corrected and the facility has been re-inspected by FDA.

You should notify this office in writing, within fifteen (15) working days of the receipt of this letter, of the specific steps that you have taken to prevent a recurrence of the cited deficiencies. Your response should include a discussion of any delays you foresee in achieving correction and a deadline by which correction can be expected. Your response should be directed to:

Randall P. Zielinski Interstate Travel Specialist Food and Drug Administration 1431 Harbor Bay Parkway Alameda, CA 94502-7070

You may wish to fax your response to Mr. Zielinski at (510) 337-6703.

Sincerely,

Dennis K. Linsley
District Director

San Francisco District

Enclosures:

- Form FDA 483
- Form FDA 2528

cc: Marc A. Gagarin, Chief Engineer
Guam International Airport Authority
P.O. Box 8870
Tamuning, Guam 96931